From: Jeffrey C Heffelman (Generation - 3) [/O=DOMINION/OU=EXCHANGE ADMINISTRATIVE GROUP

(FYDIBOHF23SPDLT)/CN=RECIPIENTS/CN=JEFFRE3]

Sent: 4/4/2015 3:45:14 PM

To: Ed Baine (Generation - 3) [/O=DOMINION/OU=EXCHANGE ADMINISTRATIVE GROUP

(FYDIBOHF23SPDLT)/CN=RECIPIENTS/CN=Edwar62]

Subject: Fwd: Ash Pond ABC inspection 03/31/15

Fyi. John Cima not concerned yet. The sandbags are causing water to pond in A pond. Before water just flowed out the eroded area. However, the flow under the rip rap will be a concern if it gets worse. We are to hear more next week.

Keep you informed.

Jeff

Sent from my iPhone

Begin forwarded message:

From: "Jeffrey R Marcell (Generation - 3)" < jeffrey.r.marcell@dom.com>

Date: April 4, 2015 at 2:42:48 PM EDT

To: "Jeffrey C Heffelman (Generation - 3)" < Jeffrey.C.Heffelman@dom.com

Subject: Re: Ash Pond ABC inspection 03/31/15

John Cima came out, he's not overly concerned, with the rip-rap and bags in place the 'A' pond is holding water, however, the flow under the rip-rap is a concern should it start to increase in flow rate.

From a legal/environmental standpoint it is a concern, will receive some guidance next week

Sent from my iPhone

On Apr 4, 2015, at 14:02, Jeffrey C Heffelman (Generation - 3) < <u>Jeffrey.C.Heffelman@dom.com</u>> wrote: Any update?

Sent from my iPhone

Begin forwarded message:

From: "Ed Baine (Generation - 3)" < < ed.baine@dom.com >

Date: April 4, 2015 at 12:08:46 PM EDT

To: "Jeffrey C Heffelman (Generation - 3)" < Jeffrey.C.Heffelman@dom.com

Subject: RE: Ash Pond ABC inspection 03/31/15

Any update or concern?

From: Jeffrey C Heffelman (Generation - 3) **Sent:** Wednesday, April 01, 2015 5:37 AM

To: Ed Baine (Generation - 3)

Subject: Fwd: Ash Pond ABC inspection 03/31/15

Sent from my iPhone

Begin forwarded message:

From: "Michael J Winters (Generation - 34)" < Michael.J.Winters@dom.com >

Date: March 31, 2015 at 5:30:11 PM EDT

To: "Jeffrey R Marcell (Generation - 3)" < jeffrey.r.marcell@dom.com>

Cc: "Jeffrey C Heffelman (Generation - 3)" < Jeffrey.C.Heffelman@dom.com>, "Doug Wight (Generation - 34)"

<doug.wight@dom.com>

Subject: RE: Ash Pond ABC inspection 03/31/15

John Cima is going out to Possum tomorrow. He will take a look at the area A sand bags.

From: Jeffrey R Marcell (Generation - 3) **Sent:** Tuesday, March 31, 2015 5:09 PM **To:** Michael J Winters (Generation - 34)

Cc: John Cima (Generation - 34); Jeffrey C Heffelman (Generation - 3); Kenneth Roller (Services - 6)

Subject: RE: Ash Pond ABC inspection 03/31/15

Attached.

Discharge (seeping) at C Pond, decreasing from previous inspection. Standing water around weir.

Standing water behind sand-bags at 'A' with seeping flow under bags in the entire area. The flow is audible and appears to be coming from under the rip-rap, similar to a "babbling brook". In addition, the southern edge of the 'A' pond interior, from the SE corner to the sandbags, is holding water, something that was not seen last year.

No recent precipitation. Last storm event was 03/26-03/27 and produced roughly 0.7" of rain.

Let me know if you have any questions.

Jeff Marcell
Environmental Supervisor
Possum Point Power Station
Ladysmith & Remington CT Sites
703-441-3813 (phone)
8-795-3813 (tie)
703-441-3897 (fax)